Approved For Release 2007/10/26 : CIA-RDP80T01471R001300050008-6	25X1
SCUKE!	25 X 1
K-6621 NPIC/CSD-605/65 1 DECEMBER 1965	25 X 1
PAGE 3 OF 6	23/1
HIGHWAY BRIDGE OVER SONG CAU	
BAC CAN, NORTH VIETNAM	
2209N - 10550E	25X1
1. PRE-STRIKE PHOTOGRAPHY OF	25X1
REVEALS A FOUR-SPAN CONCRETE AND STEEL COMBINATION HALF-THROUGH AND DECK-	_
TYPE BRIDGE OVER THE SONG CAU (RIVER), JUST NORTH OF BAC CAN ON ROUTE 3.	
AN AIRFIELD (BAC CAN AIRFIELD, IS OBSERVED JUST NORTH OF	25 X 1
BAC CAN AND EAST OF ROUTE 3. THE CITY OF BAC CAN AND THE HIGHWAY BRIDGE	
ARE HEAVILY DEFENDED BY AUTOMATIC WEAPONS POSITIONS AND LIGHT ANTIAIRCRAFT	
SITES.	
2. STRIKE DATA REPORTS THAT THE BRIDGE WAS STRUCK BY SIXTEEN US AIR	
FORCE AIRCRAFT SUPPORTED BY TWENTY-FIVE ADDITIONAL AIRCRAFT. ORDNANCE EX-	
PENDED CONSISTED OF THIRTY-TWO 3000 POUND GENERAL PURPOSE BOMBS.	
3. POST-STRIKE PHOTOGRAPHY OF	_{RE-} 25X1
VEALS EVIDENCE OF AN ATTEMPTED STRIKE AGAINST THE BAC CAN HIGHWAY BRIDGE.	THE
BRIDGE STRUCTURE ITSELF APPEARS UNDAMAGED BUT THE SOUTHERN APPROACH IS INTE	R-
DICTED.	
THE MAJORITY OF THE DAMAGE RESULTING FROM THE STRIKE IS CENTERED IN AN	
AREA JUST SOUTHWEST OF THE BRIDGE. IN THIS SECTION OF BAC CAN AT LEAST FIF	TY-

THE MAJORITY OF THE DAMAGE RESULTING FROM THE STRIKE IS CENTERED IN AN AREA JUST SOUTHWEST OF THE BRIDGE. IN THIS SECTION OF BAC CAN AT LEAST FIFTY-ONE THATCH AND WOODEN HUTS ARE DESTROYED, NINE HUTS SUFFERED STRUCTURAL DAMAGE, AND AT LEAST THIRTY-FIVE SUSTAINED LIGHT ROOF DAMAGE. (PART OF THE LATTER DAMAGE AFFECTED BUILDINGS ASSOCIATED WITH A SMALL SAW MILLING INDUSTRY AND

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.

SECRE

Approved For Release 2007/10/26 : CIA-RDP80T01471R001300050008-6		25 X 1
		25 X 1
K-6621	NPIC/CSD-605/65 1 DECEMBER 1965 PAGE # OF 6	25X1

ANOTHER SMALL UNIDENTIFIED INDUSTRY IN THE AREA).

TWO ADDITIONAL AREAS WERE STRUCK IN AN AREA SOUTHEAST OF BRIDGE.

AT LEAST NINE HUTS ARE DESTROYED; AND IN AN AREA APPROXIMATELY 500 YARDS

NORTH OF THE BRIDGE FIVE HUTS ARE DESTROYED AND THREE BUILDINGS ARE DAMAGED.

PERSONNEL ARE OBSERVED MANNING AUTOMATIC WEAPONS POSITIONS AND LIGHT ANTIAIRCRAFT SITES AROUND THE CITY AND BRIDGE.

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.



PAGES 7

PAGE / OF COPY 3 OF

25X1

25X1

HIGHWAY BRIDGE OVER SONG THUONG LANG MET, NORTH VIETNAM 2130N 10621E

1. PRE-STRIKE PHOTOGRAPHY OF TROJAN HORSE	REVEALS	25X1
A HIGHWAY BRIDGE ON ROUTE 1 SPANNING THE SONG THUONG (RIVER), LOCATE	ED ON THE	
NORTH EDGE OF LANG MET AND APPROXIMATELY 40 NM NORTHEAST OF HANOI.		

- 2. STRIKE DATA REPORTS THAT THE HIGHWAY BRIDGE WAS STRUCK ON 05 OCTOBER

 1965 BY EIGHTEEN USAF F-105 AIRCRAFT SUPPORTED BY THIRTY-FIVE OTHER AIRCRAFT.

 ORDNANCE EXPENDED CONSISTED OF THIRTY 3000-POUND GENERAL PURPOSE BOMBS.
- 3. POST-STRIKE PHOTOGRAPHY OF REVEALS TWO SPANS AND THE CONCRETE SUPPORTING PIERS ON THE EASTERN END OF THE BRIDGE TO HAVE BEEN DESTROYED, AND THE EAST AND WEST APPROACHES TO THE BRIDGE TO HAVE BEEN INTERDICTED.
- 4. THE DAMAGE TO THE HOUSING LOCATED ON BOTH SIDES OF THE SONG THUONG (RIVER) IN THE VICINITY OF THE BRIDGE IS AS FOLLOWS:

AREA 1: NO MAJOR STRUCTURAL DAMAGE IS NOTED TO THE HOUSING LOCATED ALONG ROUTE 1, 300-600 YARDS SOUTHWEST OF THE BRIDGE; HOWEVER, FOURTEEN OF THE BUILDINGS HAVE SUSTAINED LIGHT-TO-MODERATE ROOF DAMAGE.

AREA 2: APPROXIMATELY FIFTEEN BUILDINGS/HUTS ARE DESTROYED,

APPROXIMATELY TWELVE BUILDINGS/HUTS HAVE SUSTAINED STRUCTURAL

DAMAGE, AND APPROXIMATELY TWENTY-FIVE BUILDINGS/HUTS HAVE SUSTAINED

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.

SECRET

25X1

25X1

K-6622

NPIC/CSD 605/65 1 DECEMBER 1965 PAGE 2

LIGHT-TO-MODERATE ROOF DAMAGE IN THE HOUSING AREA LOCATED ON EITHER SIDE OF ROUTE 1 FROM THE WESTERN TERMINUS OF THE HIGHWAY BRIDGE TO A POINT 300 YARDS TO THE WEST.

AREA 3: APPROXIMATELY TWENTY SMALL HUTS ARE DESTROYED AND APPROXIMATELY TEN SMALL HUT-TYPE BUILDINGS HAVE SUSTAINED LIGHT-TO-MODERATE ROOF DAMAGE IN THE HOUSING AREA LOCATED ON EITHER SIDE OF ROUTE 1 FROM THE EAST END OF THE HIGHWAY BRIDGE TO A POINT APPROXIMATELY 300 YARDS EAST OF THE BRIDGE.

AREA 4: ELEVEN BUILDINGS HAVE SUSTAINED LIGHT-TO-MODERATE

ROOF DAMAGE IN THE HOUSING AREA LOCATED WITHIN LANG MET ON THE NORTH

SIDE OF ROUTE 1 FROM 300-500 YARDS EAST OF THE HIGHWAY BRIDGE.

5. COLLATERAL REPORTS THAT THE LANG MET HIGHWAY BRIDGE CONTROLS TRAFFIC BETWEEN KEP AND LANG SON, WHERE ROUTE LA COULD BE USED AS AN ALTERNATE TO THE HANOI - LANG SON RAIL LINE. THE INTERDICTION OF THIS BRIDGE COULD CAUSE A SIGNIFICANT REDUCTION IN THROUGH CAPACITY ON ONE OF THE MOST IMPORTANT ROAD ACCESSES, FROM SOUTHERN CHINA TO HANOI VIA LANG SON.

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of is <u>sue.</u>

SEGREI

Approved For Release 2007/10/26 : CIA-RDP80T01471R001300050008-6	25 X 1
	25X1
NPIC/CSD 605/65 (REVI 1 DECEMBER 1965 PAGE_3_	
HICHWAY BRIDGE OVER SONG CAU BAC CAN, NORTH VIETNAM 2209N 10550E	25X1
1. PRE-STRIKE PHOTOGRAPHY OF	25X1
REVEALS A FOUR-SPAN, CONCRETE AND STEEL, COMBINATION HALF-THROUGH	25X1
AND DECK-TYPE BRIDGE OVER THE SONG CAU (RIVER), JUST NORTH OF BAC CAN	
ON ROUTE 3. BAC CAN AIRFIELD IS OBSERVED JUST NORTH	25X1
OF THE CITY AND EAST OF ROUTE 3. BOTH THE CITY OF BAC CAN AND THE	
HIGHWAY BRIDGE ARE HEAVILY DEFENDED BY AUTOMATIC WEAPON POSITIONS AND	
LIGHT ANTIAIRCRAFT SITES.	
2. STRIKE DATA REPORTS THAT THE BRIDGE WAS STRUCK BY SIXTEEN USAF	
AIRCRAFT SUPPORTED BY TWENTY-FIVE ADDITIONAL AIRCRAFT. ORDNANCE EXPENDED	
CONSISTED OF THIRTY-TWO 3000-POUND GENERAL PURPOSE BOMBS.	
3. POST-STRIKE PHOTOGRAPHY OF	25X1
REVEALS EVIDENCE OF AN ATTEMPTED STRIKE AGAINST THE BAC CAN HIGHWAY BRIDGE.	
THE BRIDGE STRUCTURE ITSELF APPEARS UNDAMAGED BUT THE SOUTHERN APPROACH IS	
INTERDICTED.	
THE MAJORITY OF THE DAMAGE RESULTING FROM THE STRIKE IS CENTERED IN	
AN AREA JUST SOUTHWEST OF THE BRIDGE. IN THIS SECTION OF BAC CAN AT	
LEAST FIFTY-ONE THATCH ROOFED AND WOODEN HUTS ARE DESTROYED, NINE HUTS	
SUFFERED STRUCTURAL DAMAGE, AND AT LEAST THIRTY-FIVE HUTS SUSTAINED LIGHT	,
ROOF DAMAGE. PART OF THE LATTER DAMAGE AFFECTED BUILDINGS ASSOCIATED WITH	

25X1

25X1

only for the reporting period as indicated by the date of issue.

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid

25X1

SECRET

K-6621

NPIC/CSD 605/65 1 DECEMBER 1965 PAGE 4

A SMALL SAW MILLING INDUSTRY AND ANOTHER SMALL UNIDENTIFIED INDUSTRY IN THE AREA.

TWO ADDITIONAL AREAS WERE STRUCK SOUTHEAST OF THE BRIDGE IN WHICH AT LEAST NINE HUTS ARE DESTROYED; AND IN AN AREA APPROXIMATELY 500 YARDS NORTH OF THE BRIDGE, FIVE HUTS ARE DESTROYED AND THREE BUILDINGS ARE DAMAGED.

PERSONNEL ARE OBSERVED MANNING AUTOMATIC WEAPON POSITIONS AND LIGHT ANTIAIRCRAFT SITES AROUND THE CITY AND BRIDGE.

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of <u>issue</u>.

SECRE

Approved For Release 2007/10/26 : CIA-RDP80T01471R00	25 X 1
Approved 1 of recease 2007/10/20 . OIA-RD1 0010147 IROU	25X1
K-66°2 TROJAN HORSE	NPIC/CSD-1 /-> 1 DECEMBER 1965 25X1
	PAGES 7 25X1 PAGE 7 7
	COPY 2

HIGHWAY BRIDGE OVER SONG THUONG LANG MET, NORTH VIETNAM 2130N - 10621E

1. PRE-STRIKE PHOTOGRAPHY, TROJAN HORSE		REVEALS
THE LANG MET HIGHWAY BRIDGE OVER THE SONG THUONG (RIVER) LOCATED	ON	THE
NORTH EDGE OF THE CITY ON ROUTE 1, APPROXIMATELY 40 NM NORTHEAST	OF	HANOI.
THE BRIDGE IS A FOUR-SPAN, WOODEN DECK-TYPE WITH CONCRETE PIERS	6uD	ABUTMENTS.

- 2. STRIKE DATA REPORTS THAT THE LANG MET HIGHWAY BRIDGE OVER THE SONG THUONG WAS STRUCK ON Ø5 OCTOBER 1965, BY EIGHTEEN USAF F 105 AIRCRAFT SUPPORTED BY 35 OTHER AIRCRAFT. ORDNANCE EXPENDED CONSISTED OF THIRTY 3000 POUND GENERAL PURPOSE BOMBS.
- 3. POST-STRIKE PHOTOGRAPHY OF REVEALS TWO SPANS AND THE CONCRETE SUPPORTING PIERS ON THE EAST END OF THE BRIDGE HAVE BEEN DESTROYED. THE EAST AND WEST APPROACHES TO THE BRIDGE HAVE BEEN INTERDICTED.
- 4. DAMAGE TO HOUSING ON BOTH SIDES OF THE SONG THUONG IN THE VICINITY OF THE BRIDGE IS EVIDENT:
 - AREA 1: (SECTION ALONG ROUTE 1, 300-600 YARDS SOUTHWEST OF THE BRIDGE).

 NO MAJOR STRUCTURAL DAMAGE TO HOUSING IS NOTED IN THIS AREA. FOURTEEN

 BUILDINGS HAVE SUSTAINED LIGHT TO MODERATE ROOF DAMAGE.

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.

25**X**1

25X1

25X1

Approved For Release	2007/10/26 : CIA-RDP	80T01471R001300050008-6

es and affin the time of

25 X 1
25X1
25X1
25X1

K-6622			
TROJAN	HORSE		

NPIC/CSD-605/65 1 DECEMBER 1965

PAGE 2 OF 7

AREA 2: (SECTION ON EITHER STDE OF ROUTE 1 FROM THE WEST END OF LANG

MET HIGHWAY BRIDGE TO A POINT 300 YARDS WEST OF THE BRIDGE). APPROXIMATELY

TWENTY-FIVE BUILDINGS/HUTS HAVE SUSTAINED LIGHT TO MODERATE ROOF DAMAGE,

APPROXIMATELY TWELVE BUILDINGS/HUTS HAVE SUSTAINED STRUCTURAL DAMAGE,

AND APPROXIMATELY FIFTEEN BUILDINGS/HUTS HAVE BEEN DESTROYED. LANG

MET HIGHWAY BRIDGE OVER THE SONG THUONG HAS BEEN DESTROYED.

AREA 3: (SECTION ON EITHER SIDE OF ROUTE 1 FROM THE EAST END OF LANG

MET HIGHWAY BRIDGE TO A POINT APPROXIMATELY 300 YARDS EAST OF THE BRIDGE).

APPROXIMATELY TWENTY SMALL HUTS ARE DESTROYED AND APPROXIMATELY TEN SMALL

HUT TYPE BUILDINGS HAVE SUSTAINED LIGHT TO MODERATE ROOF DAMAGE.

AREA 4: (SECTION OF LANG MET FROM 300 YARDS TO 500 YARDS EAST OF LANG

MET HIGHWAY BRIDGE ON THE NORTH SIDE OF ROUTE 1).

ELEVEN BUILDINGS HAVE SUSTAINED LIGHT TO MODERATE ROOF DAMAGE.

5. COLLATERAL REPORTS THAT THE LANG MET HIGHWAY BRIDGE CONTROLS TRAFFIC BETWEEN KEP AND LANG SON WHERE ROUTE 1A COULD BE USED AS AN ALTERNATE TO THE HANOI-LANG SON RAIL LINE. INTERDICTION OF THIS BRIDGE WILL CAUSE A SIGNIFICANT REDUCTION IN THROUGH CAPACITY ON THE MOST IMPORTANT ROAD ACCESS FROM SOUTHERN CHINA TO HANOI VIA LANG SON.

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue

25**X**1